

DOSYA NO (FILE NUMBER) : 24-H25 / ITEM 11

STOK NO (NIIN) : 015664512

MALZEME ADI (MATERIAL NAME) : TRANSDUCER,ULTRASONIC TEST

KULLANILDIGI SISTEM (SYSTEM/DEVICE USED IN) : YER DESTEK CIHAZLARI (GROUND SUPPORT DEVICES)

A1-862QA-MDB-100
IRAC 7 – 19 MAY 2010




Figure 3-7B – Ultrasonic Inspection Tool I

HB-2344 Ultrasonic Inspection Tool with the lower stop positioned such that the distance between the upper face of the Tool Head and the lower face of the Locating Disk is 6.5-inches.




Figure 3-7C – Ultrasonic Inspection Tool II

HB-2344 Ultrasonic Inspection Tool with the upper stop positioned such that the distance between the upper face of the Tool Head and the lower face of the Locating Disk is 8.0-inches.




Figure 3-7D – Ultrasonic Inspection Tool Head

HB-2344 Ultrasonic Inspection Tool showing the two fasteners attaching the inspection tool head and the metal flange.

A1-862QA-MDB-100
IRAC 7 – 19 MAY 2010




Figure 3-7H – Ultrasonic Inspection Tool in Output Bevel Gear Bore